



KENTUCKY TRANSPORTATION CENTER

College of Engineering

**EVALUATION OF EDGE DRAINS
ON I-81, IN ROANOKE, VIRGINIA**



UNIVERSITY OF KENTUCKY

Research Report
KTC-96-12

EVALUATION OF EDGE DRAINS
ON I-81, IN ROANOKE VIRGINIA

by

L. John Fleckenstein
Senior Research Investigator

and

David L. Allen
Chief Research Engineer

Kentucky Transportation Center
College of Engineering
University of Kentucky
Lexington, Kentucky

The contents of this report reflect the views of the authors who are responsible for the facts and accuracy of the data presented herein. The contents do not necessarily reflect the official views or policies of the University of Kentucky, nor the Virginia Research Council. This report does not constitute a standard, specification, or regulation. The inclusion of manufacturer names and trade names are for identification purposes and are not to be considered as endorsements.

June 1996

EXECUTIVE SUMMARY

This report documents findings of the investigation of five different brands of panel edge drains installed in a test section along Interstate 81 in Roanoke, Virginia, from Milepost 154.148 to Milepost 156.11. Findings from this study indicated that closed core edge drains (Multi-Flow, Advanedge) are less likely to become damaged or distressed than the more open core drains (Contech, Akwadrain, Hydraway). Typical distress found in the more open cores was rolling over of the top row of support columns, fabric intrusion between support columns, and rolling up of the bottom row of support columns.

INTRODUCTION

In 1995, panel drains were installed on I-81, in the vicinity of Roanoke, Virginia. The panels were backfilled with a crushed granite, No. 8 aggregate. Predominately Hydaway edge drains were installed throughout the project. A two-mile test section was installed from milepost 156.110 to 154.180. Four additional edge drain products were installed in the test section. This included: Contech, Akwadrain, Advanedge, and Multi-Flow. In May 1996, personnel of the Kentucky Transportation Center (KTC) inspected the panel edge drains. This report documents the findings from this inspection.

SITE INSPECTION

On April 30, 1996, personnel from KTC and the Virginia Research Council met on I-81 to inspect the test section and to layout locations for the borescope inspection. It was observed that headwalls had not been attached to a large portion of the outlets. Eighteen of the 35 outlets inspected did not have headwalls. Headwalls had not been installed in the Contech, Multi-Flow, or Hydaway test sections (Appendix A).

BORESCOPE INSPECTION

On May 1, 1996, the panel drains were inspected with a rigid and a flexible borescope. The inspection information is contained in Table 1. Video prints showing the distress that was observed in some of the panels is contained in Appendix B. The inspection indicated that tilting or rolling of the top and bottom rows of support columns was occurring in the more open, cusped and post-type cores (Contech, Akwadrain, Hydaway). Slight to moderate fabric intrusion was also noticed in each of the three panels. It appears that approximately five to 10 percent of the core area has been reduced in the post and cusped drains due to rolling and fabric intrusion. The remaining 90 to 95 percent of the core appeared to be in good condition. It appears there was no core area loss in solid core drains. No distress was observed in the Advanedge panel. No distress was observed in the horizontal flow tubes of the Multi-Flow panel. It did appear that some of the vertical tubes of the Multi-Flow panel had been compressed.

Due to the time restraints on the inspection, the performance of the filter fabric on each panel was not fully evaluated. The inverts of the drains appeared to be relatively clean and did not contain any significant amount of siltation.

DISCUSSION

Rolling or folding of the top and bottom rows of support columns is typical behavior of the post and cusped types of drainage panels. This behavior has been duplicated using the vertical compression chamber developed at the Kentucky Transportation Center. Compression of the vertical flow tubes documented in the field inspection of the Multi-Flow panel has also been observed during vertical compression tests.

Current vertical compression flow tests being conducted at the KTC indicate that rolling of the top and bottom rows, in addition to slight fabric intrusion between support columns, can reduce the total flow capacity by approximately 2 to 4 gallons per minute (using a clean, well grade, concrete sand).

TABLE 1. DISTRESS OBSERVED IN EDGE DRAIN PANELS

PANEL TYPE	LOCATION	OBSERVED DISTRESS
CONTECH	Milepost 155.730	Slight fabric intrusion between support columns. Bottom row rolled up almost in contact with upper row. Lateral offset at mid panel.
CONTECH	Milepost 155.540	Rows 4 and 5 were slightly pushed closer together. Significant fabric intrusion occurring between rows 7 and 8.
CONTECH	Milepost 155.505	Fabric intrusion between rows 4 and 5. Lateral offset at mid panel.
ADVANEDGE	Milepost 155.384	No signs of deformation. Drain appears to be in excellent shape.
ADVANEDGE	Milepost 155.225	No signs of deformation. Drain appears to be in excellent shape.
AKWADRAIN	Milepost 154.914	5th row down support columns pushed 1/3 of the way together. Slight offset at base of panel. Slight fabric intrusion between some of the support columns.
AKWADRAIN	Milepost 154.737	Fabric intrusion occurring second row from bottom. Bottom row of support columns rolled up.
MULTI-FLOW	Milepost 154.415	Inspected top tube of drain. Appeared to be in good shape. Couldn't inspect tubes below without damaging the drain.
MULTI-FLOW	Milepost 154.405	Inspected horizontal tubes 1-3, and 7-8. Tubes appear to be in good shape. Some compression appears to be occurring in some of the vertical flow tubes.
HYDRAWAY	Milepost 154.05	Top row of support columns had rolled 1/2 way over. Moderate fabric intrusion. The bottom row had rolled up with moderate to severe fabric intrusion occurring.
HYDRAWAY	Milepost 154.03	Bottom row of support columns had rolled up. Fabric was also folded in between the support columns.

CONCLUSIONS AND RECOMMENDATIONS

It appears the headwalls not being attached has not severely damaged the panels or the filter fabric. It is recommended that the headwalls be attached when the drain is placed. Water being held in these drainage systems can do more damage than good if they are not properly installed and maintained.

Some of the fabric intrusion observed mid-panel appears to be due to lateral offsets in the panel possibly caused by irregularities in the trench wall. In comparison to past borescoped inspections of post and cusped core-type panel drains installed with excavated trench material, the drains appear to be in relatively good condition. Rolling of the top and bottom rows of support columns and some fabric intrusion will typically occur, and should not be attributed to the backfill material used on this project or the method of installation.


It is evident that the solid-core products appear to be more stable.

It is the opinion of the authors that expected core area changes and the associated reduction of flow should be addressed during design of these systems.

SYMBOL KEY



Outlet With Drain



Outlet With No Headwall



Inspected Panel Drain
With Borescope


Start Contech



155.9



155.856



155.784

Borescoped



155.730



155.641




155.575

Borescoped



155.540



155.511

Borescoped



155.505

End Contech
Start ADS



155.464

Borescoped

155.384



155.377



155.234

Borescoped

155.225



155.185



155.133



155.076



155.025

End ADS

Start Akwadrain



155.00



154.974



154.923

Borescoped



154.914



154.874



154.824



154.760

Borescoped



154.737

Akwadrain (cont)  154.713



 154.665


 154.615


 154.567

End Akwadrain
Start Multi-Flow  154.471


Borescoped  154.415

  154.405


 154.347

 154.270


End Multi-Flow
Start Monsanto



154.204



154.148




154.082




Borescoped 154.054




Borescoped 154.030



154.020



153.942



153.884


Monsanto(cont)



153.820




153.760




153.696

APPENDIX B
DISTRESS OBSERVED IN EDGE DRAIN PANELS

CONTECH




Offset Core, Mid Panel




Rolling of Bottom Posts



Fabric Intrusion, Mid Panel




Tilting of Post, Bottom of Panel




Diagonal View

Fabric Intrusion, Mid Panel




Fabric Intrusion, Mid Panel




Fabric Intrusion, Mid Panel



ADVANEDGE



Vertical View of ADS Panel



Diagonal View of ADS Panel




Water Coming Through Bottom Perforations


AKWADRAIN



Rolling of Columns, and Fabric Intrusion, Bottom



Compression Between Post



Rolling of Posts, and Fabric Intrusion, Bottom of Panel




Compression Between Post

MULTI-FLOW



View Up Through Vertical Flow Tube



View Down Through Vertical Flow Tube



Horizontal Flow Tube



Compressed Vertical Flow Tube

HYDRAWAY




Tilting of Columns, Bottom Panel




Fabric Intrusion



Fabric Intrusion




Fabric Intrusion, Bottom of Panel



Rolling of Columns, Fabric Intrusion, Bottom

Rolling of Columns, Fabric Intrusion, Bottom



Rolling of Columns, Fabric Intrusion, Bottom

